New firmware release 6.30.1.13-202505291120



For the HP Latex 630 Printer Series

July 2025

Related links: www.hp.com/go/latex/

New firmware is available to download for the HP Latex 630 Printer Series. HP recommends that all printers are upgraded to the new firmware and software as soon as possible. New printers must be upgraded during installation.

Upgrade instructions

There are three ways of updating the firmware to the latest version; either by using a USB flash drive, by using the Embedded Web Server, or using "Automatic Firmware Upgrade" from printer.

A. Firmware update using a USB flash drive

1. Download the firmware package and save it onto the USB flash drive.

• Go to: https://support.hp.com/us-en/drivers/selfservice/hp-latex-630-W-printer/2101610359 and download the latest firmware. From now on, you can download the firmware directly from HP.com and save it onto a USB flash drive.

IMPORTANT: The USB flash drive must contain only one firmware file (bdl) in the drive's root folder, with no other files, and should have at least 8 GB of capacity.

- 2. Connect the USB flash drive to the USB connector at the rear of the printer.
- 3. Go to the Control Panel and follow the Sequence: Menu>Tools>Maintenance>Firmware>USB

© Substrate Not Loaded Not Loaded Load No Pending Jobs	Menu Substrate Library Tools Settings Info	···· •/4 •/4 •/4 •/4 •/4 •/4 •/4 •/4	Toubleshooting Reports Maintenance Service	
Maintenance Restore Settings Firmware User Maintenance Service Package	firmware Firmware update not checked yet Firmware Version 6.30.1.13-202505291120 Revision 6.30.1 History USB Check			

4. On the following screen, click the file that refers to the new firmware.

Specifications of the USB flash drive:

- USB 2.0 compatible.
- Atleast8GB capacity.
- FAT 32 preformatted.
- Nohardware encryption.

B. Firmware update using the Embedded Web Server

- 1. Download the firmware package and save it onto the hard disk of the RIP PC or another computer connected to the same LAN as the printer.
- 2. Access the Embedded Web Server by entering the IP address of the printer on a web browser.
- 3. From the Embedded Web Server, select General and then Firmware update > Manual firmware update.

🍈 HP Latex 630 W		Q ()
Home Home Substrate General About the Printer Event Log	Firmware Information Firmware Update	
Country/Region Language Date and Time Power Settings Display Settings	Manual Firmware Update NOTICE The infrare cannot be used while the firmware is being updated. Upland Choose File No file those Install a Printer Undate	
Restore Default Settings	The printer can install updates that have been downloaded from the official Support Center: Follow these steps to install a new firmware release Extract the contents of the downloaded file to a folder in your computer's hard disk. Extract the contents of the downloaded file to a folder in your computer's hard disk. Select the file to update Select Tub file to update Select Tub file to update	
 Support Tools Connected Printing Accessibility 	If you have any problems during the process or want more information, contact HP Support Center:	Update

NOTE: You may be required to enter the default PIN.

 $\label{eq:NOTE: You may be required to enter the PIN, which can be found on the label at the rear of the printer.$

HP Printer Name	
P/N:######	
S/N:#########	in the second
■ PIN : #######	hpsmart.com

- 4. Browseto select the downloaded.bdl file and click Agree.
- 5. A few reboots caused by System Errors are necessary to complete the installation.

C. Firmware upgrade using "Automatic Firmware Upgrade" from printer.

1. To enable the Automatic Firmware Upgrade, go to: *Menu>Settings>Firmware Update>Auto Update Options* and select Auto Update.



NOTE: You may be required to enter the PIN, which can be found on the label at the rear of the printer.

IMPORTANT: Please note that new firmware versions will only be available on the automatic firmware upgrade server a few weeks after they are published on HP.com.

The main changes and improvements of this release:

- System improvements
- Media management
- Calibrations
- Bug fixing

Details of the improvements:

- System
 - Dark/Light color theme: *Menu>Settings>General>Display>Color Theme*



- Media management
 - Tiling Optimization improvements
 - Assisted feed & auto-deskew" automatically selected
 - Skew acceptance automatically set to "1"
 - Length accuracy improvement between tails
 - Temperature overshoot when printing from pinches and vapor curtain is open to improve temperature stability inside of the curing module.
- Calibrations
 - o Advance Plot calibration change



- Bug fixing
 - Improvements for certain occasions where the front panel may freeze when reporting an assert error.
 - Fix for F0.01.04.05, F0.02.02.03, F0.03.14.0D, F0.31.0E.02, F0.03.09.03, F0.01.03.01, F0.01.01.01, CA.E0.E0.0B, CA.3C.99.0B, CE.83.B9.0B and CE.B5.90.0B assert errors that should not occur in certain situations.