



# Firmware LION\_02\_22\_31.1 is available

For the HP DesignJet Z6 and Z9+ Pro Printer Series

December 2022

**A new firmware version, LION\_02\_22\_31.1, is available for the HP DesignJet Z6 and Z9+ Pro 64in printers. The following sections contain details of the changes.**

## New fixes included in LION\_02\_22\_31.1

- Fixed a bug with RIP software workflow causing incorrect color printing.

## Fixes and enhancements included in previous versions

### LION\_02\_22\_20.1

- Dynamic back tension to avoid skew and bubble in long plots.
- Protect front panel media list configuration workflows with Role Based Access Control.
- A new setting to enable/disable automatic End of Roll resolution.
- Diagnostic plot moved to a more visible place.
- Serial number, date, and time has been added to the front panel/EWS Usage app.
- Changed cutter button's color in Feed&Cut app.
- Substrate load animations and strings update.
- Elimination of Take-Up Reel bugs that were generated in certain print mode/roll width combinations.
- Fix for EWS access issue through internet browsers.
- AirPrint certification.
- HP Clear Film support (with silver borders).
- Support for new ICC profile synchronization tool.
- Enable media profiles editing in Embedded Web Server.
- New front panel option to allow lifting pinches.
- Add roll selection step in.
- Add new media process

### LION\_01\_21\_36.5

- Added support for new electronic components.
- Improved the reading of Maintenance Cartridge level.

#### LION\_01\_21\_36.4

- Fixed an issue with RIP software workflow leading to inaccurate color outputs.
- Fixed a bug that caused incorrect paper advance before cutting.

#### LION\_01\_21\_36.2

- Introductory version.