

Firmware LION_02_23_14.1



For the HP DesignJet Z6 and Z9+ Pro 64in Printer Series

May 2023

New versions of firmware and software for the HP DesignJet Z6 and Z9+ Pro 64in Printer Series are available to download.

HP recommends that all printers are upgraded to the new firmware and software.

New fixes included in LION_02_23_14.1

- Added support for interchangeable HDDs for TAA Compliant units (Product Number 2RM82G).
- The issue of the printhead replacement process not completing if the ink used is non-HP Original is resolved.
- Security fix linked to the [Security Bulletin HPSBPI03837](#).

Fixes and enhancements included in previous versions

LION_02_22_31.1

- Fixed a bug with RIP software workflow that caused incorrect color printing.

LION_02_22_20.1

- Dynamic back tension to avoid skew and bubble in long plots.
- Protect front panel media list configuration workflows with Role Based Access Control.
- A new setting to enable/disable automatic End of Roll resolution.
- Diagnostic plot moved to a more visible place.
- Added serial number, date, and time to front panel/EWS Usage app.
- Changed the color of the cutter's button in the Feed&Cut app.
- Substrate load animations and strings update.
- Removed the Take-Up Reel bugs that were generated in certain print mode/roll width combinations.
- Fix for EWS access issue through internet browsers.

LION_01_21_36.5

- Added support for new electronic components.
- Enhanced the reading of maintenance cartridge level.

LION_01_21_36.4

- Resolved an issue with RIP software workflow leading to inaccurate color outputs.
- Fixed a bug causing incorrect paper advance before cutting.

LION_01_21_36.2

- Introductory version.