New firmware release PLS_50_23_39.1

For the HP Latex 700 / 800 printer series

Related links: www.hp.com/go/latex/

October 2023

A new firmware version PLS_50_23_39.1 is now available to download and install for the HP Latex 700 and 800 printer series. HP strongly recommends installing this new firmware version on all units, as it includes significant improvements.

Firmware can be upgraded by downloading the firmware package from the hp.com website.

How to install the firmware

Download the firmware file from the product support page:

• <u>https://support.hp.com/us-en/drivers</u>

On the download website you can find four different files to download. This is because the FW file is compressed and divided into four parts (001, 002, 003 and 004). It is necessary to download all four parts.

NOTE: Since Windows Zip does not support split files, it will be necessary to use a third-party zip software such as WinRAR or 7.zip.

Click with the central mouse button and the download will start automatically in the download bar. Alternatively, right click on the file and select **Open in a new tab**, like in the image below.

PL	.5_26_21_27.1.rtu.7z.002		1000.0 MB 889.0 MB	Uo ك Do ك	wn wn	Open link in new tab Open link in new window
► HF 80 Multi	P Latex 700/700 W and HP Latex 00/800 W Printers Firmware i-part download	PLS_26_22_01.1	Feb 28, 2022			Open link in incognito window Save link as
PL	.5_26_22_01.1.rfu.zip.001		975.0 MB 975.0 MB	Do ىك Do يك	wn wn O	Copy link address AdBlock — best ad blocker
PL	.5_26_22_01.1.rfu.zip.003		938.8 MB	🕁 Do	wn	Inspect
PLS_26_22_01.1.rfu003 714/939 MB, 1 min left	PLS_26_22_01.1.r 842/975 MB, 21 secs	rfu002 ^	PLS_26_22_01.1.rfu001 889/975 MB, 11 secs left	^		



Once all zip files are downloaded, right click the file PLS_50_23_39.1.rfu.zip.001 and unzip it with the third-party zip software (do not use Microsoft Windows Zip). This will produce the file PLS_50_23_39.1.rfu.fmw.

Upgrade instructions

IMPORTANT: The jobs on the front panel print queue will be deleted when updating the firmware. You will need to send them again from the RIP software to have them available on the front panel job queue.

There are two options to update the firmware to the latest version.

Firmware update using a USB flash drive

1. Download the firmware package and store it on the USB flash.

(MD5: 21a3c4052aa2e234243242e5d980b965)

IMPORTANT: The USB flash drive should contain only one firmware file (.fmw) in the drive's root folder, and no other files.

- 2. Connect the USB flash drive to the USB connector at rear of the printer.
- 3. Follow the onscreen instructions on the front panel.

Specifications of the USB flash drive:

- USB 2.0 compatible
- At least 8 GB capacity
- FAT 32 preformatted
- No hardware encryption

Firmware update using the Embedded Web Server

- 1. Download the firmware package and store it on the RIP PC's hard disk.
- 2. Access the Embedded Web Server by entering the IP address of the printer on a web browser.

NOTE: You may be required to enter user and password details. Type **admin** in each field and tap **Login**.

Sign in https://15.83	6.159
Username	admin
Password	•••••
	Sign in Cancel

3. In the Embedded Web Server, select **Information** and then **Firmware update > Manual firmware update**.

ி Home	Â	The printer can install updates that have been downloaded from the official HP Support Center.
🕉 Ink	~	Poliow triese steps to install a new limiware release.
C) Substrate	~	1. Access the HP Support Center. (HP Support Center)
5 50531010		2. Locate the appropriate file and download it to your hard disk.
2 Usage	~	3. Extract the contents of the downloaded file to a folder in your computer's hard disk.
Security	~	4. Select the file to update.
About printer	^	 Use the "I AGREE" button to accept the HP license agreement and proceed to update the printer's firmware. After the firmware update is installed, the printer will restart.
Printer Information		Click to choose a file or dran it here
inter updates		
Firmware undate		If you have any problems during the process or want more information, contact your nearest support center.

- 4. Browse to select the downloaded .fmw file and click Agree.
- 5. The printer will reboot itself when the FW upgrade is completed.

Details of fixes and enhancements

Tiling optimization slider in printer FP menu.

The main new feature added on this new firmware version relates to a new slider which works in a way that optimizes the printer with the best possible settings to print tiling jobs.

It is not necessary to use any specific profile "for tiling" downloaded from media solutions locator, as with previous FW releases because every single media preset can be optimized using this slider button. The following modifications will be done if the user selects "optimize for tiling" for all supported families (Wallpaper and SAV):

- Includes an ExtraTopMargin of 200mm. The top margin is done before the 1st job and between jobs without tailgating.
- Disables cooldown movements.
- Disables warmup movements.
- The warm up process (longer and optimized for long run stability)

NOTE: The settings apply until the optimization for tiling is disabled. Note that all the other options to run the 1m stabilization plot has been removed, it only can be sent from RIP.

How to activate:

• The tiling optimization setting can be activated in the second step of loading flow, from the front panel. Substrate load: Substrate configuration.

[1048] Substrate load: Substrate type selection		[1047] Substrate load: Subst	trate configuration
Recently used	Generic Backlit Self-Adhestive Vinyi 🐱	Length To track remaining substra	teinrol Unknown 🗸
Generic Backlit Self-Adhesive Vinyl		LOADING OPTIONS	
O Generic Self-Adhesive Vinyi	1	Loading method	Assisted feed & auto-deskew 🛛 🛩
Generic Transparent Self-Adhesive Vinyl		Skew acceptance From -xx- to +xx-	- 2 +
Self-Adhesive Vinyi	~	Tring optimization Adjusts printing settings to	o Improve length stability
Paper	~	ACCESSORIES	
Textle	~	Print zone	Platen 🗸
	[276] Concel [463] Continue		[276] Cancat [463] Continue

• From Substrate source settings, with a roll loaded, the setting can be activated and deactivated inside Substrate source settings.



New Nozzle health plot.

With this new firmware release, the pattern to be printed as a nozzle health plot has been changed to prevent wrong printhead diagnostics by visually evaluation of the wrong area, where the print quality was not important in terms of printhead print quality diagnosticability. For better understanding, text has been added to some specific areas to add more clarity and all the spit bars have been removed from the pattern. All the spits to warm up the printheads will be done in the maintenance cartridge instead of in the printed pattern.

The new layout looks like the following image:



Job cancels improvement time.

The new firmware contains improvements on the cancel job timings, as it focuses on reestablishing the printer in a faster way. This is compared with previous versions, as soon as a job has been submitted, and after being completely received by the printer, and the job is cancelled. The reduction of the time is highly improved.

The users can cut the media or reprint a job in much less time than before after pressing cancel to a job that has started to print or if it is warming up to start printing.

Beacon status light review

This FW tries to correct the confusing situations with the beacon lights and change the general color code set up previously in previous firmware versions. In general terms the beacon does not fulfill its function to communicate to the user if they need to act or not.

For example: The printer beacon is continuously in Yellow when loading the material.

If the user unloads the printer after stop printing the printer beacon is continuously in Yellow, but no action is really needed at the end, this can be problematic in fleet environments as this gives the perception to the user that the printer is complex. Find below the new color code definition:

• New Definition & New Color meaning

Color	Meaning
GREEN	Default state of the printer.
YELLOW	The printer requires user intervention which, if not performed, may result in an interruption of a job.
RED	The job printing has been interrupted unexpectedly or the printer is not able to start printing the job launched.

• Activity meaning

Activity	Meaning		
STATIC	The printer is powered on and it is not printing.		
BLINKING	The printer is printing. (This status only can be possible with GREEN and YELLOW colors.)		

• Examples:

Color	Meaning	Light state	Examples
RED	Printing Job has been unexpectedly interrupted.	SOLID – Printer is Stopped FLASHING – Not Possible	System Error While Printing Out of Substrate While Printing
YELLOW	User Intervention is Needed	SOLID – Printer is Stopped FLASHING – Printer is Printing	Out of Ink Water Tank Level Low Recirculation Mode Disabled
GREEN	Printer Idle or Printing	SOLID - Printer is Stopped FLASHING - Printer is Printing	Printing as Usual

Pause workflow enhancements.

In this FW, the pause workflow has been improved. In the previous firmware versions, the user was able to pause but the system asked if the pause should take place immediately or after job has finished:



With this firmware release it has been improved, if there is a printing job, the system stops as if the user pushed the "pause now" button, but without any pop-ups.

The pause and resume queue option has also been improved on the expanded notification bar to improve the user's experience with the user interface.



Manual PH alignment enhancement

With the previous firmware versions, if you needed to quickly modify 1 value from the manual alignment you needed to reprint the full plot. This took time and media, however from this firmware release onwards it will no longer be necessary to reprint the full job to recalibrate a single alignment value, saving both time and media.



As soon as any of the values is readjusted, the "Finish" blue button (grayed out in the picture) becomes enabled.