



Firmware TYPH_10_24_13.1 is available

For the PageWide XL Pro printer series

April 2024

A new firmware release is available for all the HP PageWide XL Pro printer series. This document provides details of the new features and main fixes.

The following models of the HP PageWide XL Pro Printer series are compatible with this firmware release.

- PageWide XL Pro 5200 MFP
- PageWide XL Pro 8200 MFP
- PageWide XL Pro 10000 Printer

Download Firmware

Firmware: TYPH_10_24_13.1

- Link: <https://support.hp.com/us-en/drivers/printers>
- Drop Box Host:
 - SFTP Access: `sftp -o Port=2222 sftp://pwxlvp3@ftp.usa.hp.com`
 - HTTPS Access: <https://ftp.usa.hp.com/hprc/>
 - Login: pwxlvp3
 - Password: Pwxl2024

New functions


Implementation of the speed upgrade feature on the new SKUs for the HP PageWide XL Printer series and their accessories.

This firmware release introduces this new feature on the two latest models and integrates it with their available accessories (Folder, High-Capacity Stacker) to increase the speed at which the printer outputs media and ensures that the input of the accessory aligns with the printer's output, guaranteeing optimal performance between both.

Reboot of the printer is now available through the Front Panel.

The user now has the option to reboot the unit simply by the touching screen.

To do so, follow the path: **System -> Power options -> Printer restart.**



Folder "Fan-fold only 198" and "Fan-fold only 210" styles enabled for longer plots.

In response to customer request, it is now possible to perform the above fan folding styles for plots that exceed the length of 2.5 meters.





Image Quality Reference Plot is now supported on boards and cut sheets.

It is now possible to print this reference plot on boards and cut sheets as well as on flexible rolls.



Main fixes and improvements

- Fixed issues of Front Panel lagging when user is printing.
- Fixed reporting status being displayed incorrectly with expired supplies.
- Fixed end of roll issue when printing more than 150 copies.
- Avoided printer from entering sleep mode while it is in use.
- Fixed option "Reset to factory defaults" of the Folder not correctly being executed.
- Fixed wrong report of AirPrint test when it fails.