Firmware TYPH_11_24_35.1 is available

For the PageWide XL Pro printer series
September 2024

A new firmware release is available for the HP PageWide XL Pro series. This document details the main fixes included in the update.

Download Firmware

Firmware: TYPH_11_24_35.1

- Link: https://support.hp.com/us-en/drivers/printers

- Drop Box Host:

    - SFTP Access: sftp -o Port=2222 sftp://br4_pwxl@ftp.usa.hp.com

    - HTTPS Access: https://ftp.usa.hp.com/hprc/

    - Login: br4_pwxl

    - Password: Pwfw_br4

Main fixes and improvements

- Added a warning notification if the submitted job is longer than the actual media length available on the roll.

- Fixed an error that caused a batch of scanned jobs to disappear from the queue after different edits (such as rotation, brightness, and cropping) were applied to them.

- Fixed some scanner errors that appeared after the printer was waking up from sleep.

- Fix for job accounting bug: Corrected an error causing incorrect cost calculations.

- Fixed some sections incorrectly being translated in the EWS once the user changed the language.

- Fixed an error of the Folder not appearing in the Accessory Utilities menu unless both accessory and printer were rebooted at the same time.

- Fixed an incorrect labelling of the Folder F40 product in certain menus.