



Firmware TYPH_06_22_04.5 is available

For the HP PageWide XL Pro Printer Series

March 2022

A new firmware release is available for all new HP PageWide XL Pro printer series. This newsletter details its main fixes.

The following models are compatible with the new release:

- PageWide XL Pro 5200 MFP
- PageWide XL Pro 8200 MFP
- PageWide XL Pro 10000 Printer

This release integrates new firmware for the folder. If there is a folder, the upgrade will take approximately 25 minutes longer.

Download firmware

Firmware: TYPH_06_22_04.5.rfu.fmw

- Link: <https://support.hp.com/us-en/drivers/printers>

New functionalities

- **Optimize printing quality calibrations can be now launched from the Embedded Web Server.**

A new submenu is available in the EWS. The following calibrations can be initiated:

- Check and recover printbar
- Automatic printhead alignment
- Page length accuracy

Main fixes and improvements

- Page length inaccuracy fixed when printing from roll
- Error 8434-A454-0000 fixed when the user cancels a cut sheet load before completion
- Printer no longer shows the information of the previously loaded roll when the user cancels it before checking it
- General stability improved

- Improved workflow and stability with the sheet feeder:
 - Fixed width and length swapped for some page sizes when printing in portrait
- Folding styles now apply when reprinting a job with a different folding style from the front panel
- Folder: improved folding quality, cross-fold and fan-fold stability