



Firmware TYPH_06_22_04.8 is available

For the HP PageWide XL Pro Printer Series

April 2022

A new firmware release is available for all new HP PageWide XL Pro printer series. This newsletter details its main fixes.

The following models are compatible with the new release:

- PageWide XL Pro 5200 MFP
- PageWide XL Pro 8200 MFP
- PageWide XL Pro 10000 Printer

This firmware release integrates the same functionalities and fixes as VP2 and additional improvements.

Download firmware

Firmware: TYPH_06_22_04.8.rfu.fmw

- Link: <https://support.hp.com/us-en/drivers/printers>

Main fixes and improvements

- Sheet feeder: improvements to mitigate multipick errors
- Improvements on the cut sheet load process when using custom lengths in the front panel
- Error 802B-DB54-0000 fixed
- Solved paper jams at rear stacker printing short pages in fast mode
- Fixed “web browser unsupported” error when entering the Embedded Web Server