

# Firmware HP Cutter Control 1.3.0.0 is available

For the HP Latex Plus Cutting Solutions

July 2024

The latest build for HP Cutter Control is now available to be downloaded and installed. This new software includes new features and fixes detailed below.

Related links:  
[www.hp.com/go/latex/](http://www.hp.com/go/latex/)

Printers related to this article  
[HP Latex Plus Cutting Solutions](#)

## Where to find HP Cutter and HP Cutter Control latest build

The new version will be available at [HP.com](http://HP.com).

## Improvements on HP Cutter Control 1.3.0.0

The new version has the following improvements:

Type	Title
Improvement	Added "BarcodeServerPingTimeout".

## Barcode Server issues

Reported communication issues between HP Cutter Control and the Cutter, resulting in the Barcode Server disconnecting. This has been identified, analyzed, and addressed in this software version, providing a solution to the problem.